

Thursday, November 15, 2007

SEWER LATERAL DEFICIENCY REPORT

APPLICANT: **HOMEOWNER**
ADDRESS: **99999 SAN PABLO AVE.
EL CERRITO, CA 94530**

The Stege Sanitary District has reviewed the sanitary sewer lateral condition of the above referenced property based on a videotape of the sewer lateral.

This letter is to notify you the following problem(s) was identified and repair / replacement is required in accordance to the District Standard Specifications of the sanitary sewer lateral.

- Broken pipe
- Offset and dislocated joints
- Root intrusion
- Cleanout and/or Backflow Prevention Device (BPD) needed

REQ'D: Complete Lateral Replacement

These are the findings as evidenced by the video. We reserve the right to add additional requirements as they arise during construction. Until the required work is completed and accepted by the District, the subject sewer lateral DOES NOT comply with the District Ordinance Code and Standard Specifications.

If you have any questions, or if we can provide any other assistance, please call us at (510) 524-4668.

*Thank you,
STEGE SANITARY DISTRICT*

*Arvin Gonzales
Engineering Tech II / Inspector*